

Oil Field Environmental Incident Summary

Incident: 20160712203751 **Date/Time of Notice:** 07/12/2016 20:37

Responsible Party: Tracker Resource Development III, LLC

Well Operator: TRACKER RESOURCE DEVELOPMENT III, LLC

Well Name: Chase 21-30H Tank Battery

Field Name: SPOTTED HORN

Well File #: 17197

Date Incident: 7/7/2016 **Time Incident:** 12:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 94

Sec: 30

Qtr: NE NW

Location Description: Oil discharge into flare pit. Flare pit is located west of heater treater on north edge of facility/well site.

Submitted By: Larry Bryant

Received By:

Contact Person: Larry Bryant
1050 17th Street Suite 2200
Denver, Colorado 80265
303-534-9513, CO 80265

General Land Use: Pasture

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.7 Mile

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	18	Gallons				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk was found.

Areal Extent:

Discharged oil was contained in the pit and burned except for some oil mist north of flare pit.

Potential Environmental Impacts:

No potential environmental impact was found.

Action Taken or Planned:

Daily well site inspections are conducted to visually monitor production rates, proper equipment performance, inspect for potential leaks, and potential equipment failures. Immediate response to possible equipment failure will result in the required site equipment being shut down and isolated safely. Any equipment found to be malfunctioning will be evaluated to be replaced or repaired.

Wastes Disposal Location: No waste was present to recover.

Agencies Involved: Local Fire Department

Updates

Date: 7/13/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, there was a release of oil to the flare causing a fire. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.